



## CENTRE BEARINGS




*Mercedes Benz W204*



*Hyundai iLoad*



<i>Part No:</i>	<b>MB-30-0981</b>
<i>Bearing Dia:</i>	<b>30mm</b>
<i>Bolt Centres:</i>	<b>182mm</b>
<i>Centre Height:</i>	<b>55.5mm</b>
<i>Application:</i>	<b>Mercedes Benz E Series 2009- and C Series 2007-2015 including C63 AMG 2010-</b>
<i>OEM No:</i>	<b>204 410 0981, 204 410 0981 S1, 204 410 1181 S1, 204 410 1581 S1</b>



<i>Part No:</i>	<b>HY-30-4H000</b>
<i>Bearing Dia:</i>	<b>30mm</b>
<i>Bolt Centres:</i>	<b>170mm</b>
<i>Centre Height:</i>	<b>22.5mm</b>
<i>Application:</i>	<b>Hyundai iLoad, iMax 2008 on</b>

[www.hardyspicer.com.au](http://www.hardyspicer.com.au)

**Ph: 1300 304 673**



• HOSE • FITTINGS • DRIVESHAFTS

### Central Support Group

17-31 Discovery Road, Dandenong South, 3175

Ph: (03) 9794 1900 Fax: (03) 9706 9928

ABN 52 099 707 856

Email: [hspicer@hardyspicer.com.au](mailto:hspicer@hardyspicer.com.au)

Web: [www.hardyspicer.com.au](http://www.hardyspicer.com.au)

### Branch Locations

#### Western Australia

Perth	49 Banksia Road, Welshpool 6106	Ph: (08) 9258 6300
Kalgoorlie	7 Keogh Way, Kalgoorlie 6430	Ph: (08) 9091 1443

#### South Australia

Adelaide	2/479-481 South Road, Regency Park, 5010	Ph: (08) 8349 6400
----------	--	--------------------

#### Victoria

Dandenong	17-31 Discovery Road, Dandenong South, 3175	Ph: (03) 9799 3250
Campbellfield	174 Fairbairn Road, Sunshine West 3020	Ph: (03) 9357 0233

#### Tasmania

Hobart	10 Duncan Street, Montrose 7010	Ph: (03) 6272 6907
--------	---------------------------------	--------------------

#### New South Wales

Sydney	37A Heathcote Road, Moorebank 2170	Ph: (02) 9600 6333
Newcastle	2 Canavan Drive, Beresfield 2322	Ph: (02) 4964 4955

#### Queensland

Eagle Farm	45 Harvey Street North, Eagle Farm 4009	Ph: (07) 3166 2500
Darra	12 Pradella Street, Darra 4076	Ph: (07) 3117 2800
Mackay	43 Margaret Vella Drive, Mackay 4740	Ph: (07) 4914 2100
Townsville	602 Ingham Road, Bohle 4818	Ph: (07) 4795 3400